

Home Page - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes... Go

Address <http://altdba48.geps.ge.com/2038/tops3/topsfirst.jsp>

Links [Inspection\[1\].gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Visto](#) [Free Yahoo](#) [Google](#)

TOPS³

Home

TOPS Home

Update Profile

Operations


Reference

EHS
Quality

Inspection and Repair Services

Welcome :

Site :



Receive

102



Process

103

Receive Job - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes...

Address http://alldb48.geps.ge.com/2038/tops3/tops/Receive.jsp

Links Inspection1[1].gif IM Quality Procedures Manual IM Quality Procedures Manual IE Quality Manual Customizer Links Free Holmat Free Visio Free Yahoo Free Google

TOPS³

Home

T&RS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. COE

ST COE

Inspection and Repair Services

Receive Job

Quantity 3 S/N Prefix * AE Dwg# * 103E3026P001 * Optional

Select the Job# :
Job# 31298 | GENERAL ELECTRIC | (14) F/9E FUEL NOZ Description

OR

Select the Temporary Job# :
Job# Description

OR

If Job# is not Available :
New Temp Job# 205

Cancel

22 Hierarchical Menu Trees Created

Internet zone

Receive Parts - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Stop Refresh Home Search Favorites History Mail Print Edit

Address <http://alldb48.geps.ge.com/2038/tops3/topsReceiveFinish.jsp>

Links [Inspection\[1\].gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Yahoo](#) [Free Visio](#) [Free Yahoo](#) [Boogle](#)

Yahool Mes Go

TOPS³

Home

TERS Home

Update Profile

Operations

Planning

Reports

Reference

EHS
Quality
PAC
DART
Gen. COE
ST COE

Inspection and Repair Services

Receive Parts

Job# 31298
Customer GENERAL ELECTRIC
Description (14) F9E FUEL NOZ
Segment PG,GAS

302

	Drawing #	Serial #	Tag #
1	2077	AWER456	2345
2	2077	ASER	5678
3	2077	ASDR	6789
4	2077	292	6735
5	103E3026P001	AE	
6	103E3026P001	AE	
7	103E3026P001	AE	
8	103E3026P001	AE	
9	103E3026P001	AE	
10	103E3026P001	AE	

303

Add Part [Attach File](#) Temp Save

304 305 306

Fig 3

TOPS3 EEE00650

400

Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Stop Refresh Home Search Favorites History Mail Print Edit

Address <http://alldba48.geps.ge.com/2038/tops3/topsReceiveFinish.jsp>

Links Inspection[1].gif JIM Quality Procedures Manual GE Quality Manual Free Holmail Free Yahoo Free Yahoo Google

Go Yahoo Mes

TOPS³

[Home](#)[I&RS Home](#)[Update Profile](#)[Operations](#)[Planning](#)[Reports](#)[Reference](#)

[EHS](#)[Quality](#)[PAC](#)[DART](#)[Gen. One](#)[ST COE](#)

Repair Services

402-

ive Parts

Description	Segment	Serial #	Tag #
(14) F8E FUEL NOZ	PG,GAS	ER456	2345
		ER	5678
		DR	6789
			6735

Choose file

Look in: Desktop

business dev
business.Test
Case 1 doc
Copy of matrix.Attest2
EditPlus 2
EnatrixMethods.java

File name

Files of type: All Files (*.*)

Open Cancel

103E3026P001 AE

Add Part Attach File Temp Save

305

TOPS 3.0 EEE0660

500

Office

Microsoft

Home Page - Microsoft Internet Explorer provided by EE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History Favorites

Address http://atdiba48.geips.ge.com:2038/tops3/topsFirst.jsp

TOPS³

Home

IGRS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART


Gen. COE

ST COE


Inspection and Repair Services

Welcome :


Site :



Planning



Reports



Approval

502

504

503

Internet

Start

22 Hierarchical Menu Trees Created

Inbox - Microso...

Microsoft Powe...

FW: Test Script...

Home Page - ...

11:24 AM

Fig 5

TOPICS "E/EE/660"

600

601

603

602

Planning - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History Favorites

Address http://alldba48.geps.ge.com:2036/tops3/topsPlanning.jsp

Office

Microsoft

TOPS³

Home I&RS Home Update Profile Operations Planning Reports

EHS Quality PAC DART Gap COE ST COE

Inspection and Repair Services

Planning Search

Select the Available Job#

Job#

Customer

Description

30481 | TRANSCO | F3LP ROTOR

Segment

Component

Customer

Drawing #

Narrow Search

Plan Information

Standard Plan

SP20001 | 7E11 Rotor

OR

Previously Built Plan

Next Cancel

Start

22 Hierarchical Menu Trees Created

Inbox - Mic... Planning - ... Microsoft P... FW: Test S... zip

Internet

11:54 AM

Fig 6

7001

700

Planning Parts - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History

Address http://aldiba48.geps.ge.com:2038/tops3/topsPlanningParts.jsp

Office

Microsoft

7001

700

TOPS³

Home I&RS Home Update Profile Operations Planning Reports Reference EHS Quality PAC DART Gen. COE STCOE

Inspection and Repair Services

Planning Assembly -702

Assembly description -704

Job# 30481 Plan 30481-SP20001
Segment PG,GAS Customer TRANSCO

Parts Structure

- 2077-30481
- 2077-AS12345
- 2077-AS12346
- 2077-AS12347

Drawing # Serial # Component

Attach >> Detach >>

Part Description

Available 705

Selected

SubPlan Description

1 | CR Receive & Inspect
10 | Turbine Rotor Disassembly
11 | Turbine Thru Bolts
12 | Turbine Pieces
13 | Turbine Rotor Assembly
2 | CR Clean & NDT
3 | CR Machine & Balance
4 | CR Disassembly
5 | Comp Wheel Full Reblade

>>> <<< All

SubPlan Description

706

Next Cancel

22 Hierarchical Menu Trees Created

Start >> Planning P... Microsoft P... FW: Test S... 2p

Internet

11:57 AM

F.87

900

TOPOT20" EEE0660

Office

Microsoft

Approve Plan - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Forward Stop Search History

Address http://atldb48.geips.ge.com:2038/tops3/topsApprove.jsp

TOPS³

Home

ARS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. EOE

ST EOE

Inspection and Repair Services

Approve

901

Plan for review

Method Sheet

Load

Approve

Inspection Form

Cancel

Start

Inbox - Mic...

Approve P...

Microsoft P...

FW: Test S...

zip

Internet

11:59 AM

Fig 9

TOPP20" ECE0660

1000

Approve Planning Parts - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back

Forward

Search

History

Go

Links

Address <http://atl01a48.geps.ge.com:2038/tops3/topsApprovePlan.jsp>

TOPS³

Home

I&RS Home

Update Profile

Operations

Planning

Reports

Reference

EHS

Quality

PAC

DART

Gen. COE

ST COE

Inspection and Repair Services

Approve Plan Steps

List of steps Plan

T00001-SP00005

Created for :

T00001 Part Type Bucket

Drawing #

1001

1002

1003

NO SUBPLANS ARE ATTACHED

Options

Reason for decline !

Accept

Decline

Finish

22 Hierarchical Menu Trees Created

Start

Inbox - Mic...

Approve Pla...

Microsoft P...

FW: Test S...

zip

Internet

12:01 PM

Fig 10

TOP 20" EEE0550

1102

Office Microsoft

Approve Plan - Microsoft Internet Explorer provided by GE Power Systems

File Edit View Favorites Tools Help

Back Search History

Address <http://atldb48.geps.ge.com:2038/tops3/topsApproveMSheet.jsp>

Go Links

TOPS³

Inspection and Repair Services

Approve Method Sheet

Method# View

Approve Reject

Finish Cancel

Home I&RS Home Update Profile Operations Planning Reports Reference

EUS
Quality
PAC
DART
Gen. COE
ST COE

22 Hierarchical Menu Trees Created

Start Inbox - Mic... Approve P... Microsoft P... JFW: Test S... zip

Internet

12:01 PM

Fig 11


Process Steps - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes.

Address <http://atldb48.geps.ge.com/2038/tops3/tops/ProcessJob.jsp>

Links [Inspection1\[1\].gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Yahoo](#) [Google](#)



Inspection and Repair Services

1201

1202

Process Job

Job# 31898 Plan 31898-SP00002

Customer GENERAL ELECTRIC Component Rotor

Check job status details ~1203

Select step to proceed with

1204

Sub Plan	Step	OpCode	Duration	Description	Select
1	010	BA01		Receive Buckets Issue receiving report	<input type="checkbox"/>
1	020	BZ01		QC TOLLGATE *	<input type="checkbox"/>
1	030			TECH TO REVIEW DATA AND ADVISE NEXT OPERATION	<input type="checkbox"/>
1	040	BA02		Issue incoming visual inspection report	<input type="checkbox"/>
1	050	BA05		Clean buckets	<input type="checkbox"/>
1	060	BA07		Issue incoming FPI report	<input type="checkbox"/>
1	070	BA10		Dimensionally inspect bucket	<input type="checkbox"/>

Back Next Close

Fig 12

TOPPLOT E2E0660

1300

Process - Parts Status - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes

Address http://altdba48.geps.ge.com/2038/tops3/topsShowProcessPartStatus.jsp

Links Inspection111.gif IM Quality Procedures Manual GE Quality Manual Customize Links Free Hotmail Free Yahoo Free Yahoo Edit Google

TOPS³

Home

1&RS Home

Update Profile

Operations

Reference

EHS Quality

Inspection and Repair Services

Process - Parts Status

Sub Plan Step Drawing# Serial# Tag# Hold State

1 010 2077-TYR4356 ServiceRunning

Back

22 Hierarchical Menu Trees Created

Internet zone

Fig 13

Address <http://altdba48.geps.ge.com/2038/tops3/topsProcessExecution.jsp>

Links [Inspection111.gif](#) [IM Quality Procedures Manual](#) [GE Quality Manual](#) [Customize Links](#) [Free Hotmail](#) [Free Yahoo](#) [Free Yeto](#) [Google](#)

Back Refresh Home Search Favorites History Mail Print Edit Yahoo! Mes

Process Job

RO #: 31898 ~ 1402

Customer: GENERAL ELECTRIC

Sub Plan: 1 Step: 010

Drawing: 2077

Component: Rotor

Op.Code: BAD1 Description: Receive Buckets.
Issue receiving

Select any of the following:

Fill Inspection Form

Add Additional Form

Attach File View File

Job Log

View Update

Available Parts

Work Complete >>

<< Undo Complete

Select All

Parts Hold

Voucher

Hours

Complete Parts

< Back Finish Cancel




Fig 16




Fig 17

09503373.071001
T00120'E2EE0660




Fig 18




Fig 19

09903373.074004




Fig 20




Fig 21